

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

1469
ENE
> 1
1.855 mi.
9794 ft.

**SANDY FOLLOW UP
2405 VOORHIES AVE
BROOKLYN, NY**

**NY Spills S112808734
N/A**

**Relative:
Higher**

**Actual:
10 ft.**

SPILLS:

Name: SANDY FOLLOW UP
Address: 2405 VOORHIES AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1213843 / 2013-06-28
Facility ID: 1213843
Facility Type: ER
DER Facility ID: 432373
Site ID: 477057
DEC Region: 2
Spill Cause: Storm
Spill Class: C3
SWIS: 2401
Spill Date: 2012-12-22
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2012-12-22
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-12-22
Spill Record Last Update: 2013-06-28
Spiller Name: DIACZOK, CATHERINE
Spiller Company: STORM
Spiller Address: 2405 VORRHIE AVE
Spiller Company: 999
Contact Name: DIACZOK, CATHERINE

DEC Memo: "left a messege for Catherine.(sr) ** left a messege again for Catherine on 01/08/2013** ** Left messege for Catherine on 02/14/13 again** ** This spill report was created for tracking purposes related to the Department's Hurricane Sandy emergency response efforts.** Inspected the site on 06/26/13, no body was home, could not get access to the basement.(sr)"

Remarks: "oil film left on basement floor - clean up pending - needs clearance - for rapid repair to come in and do work"

All Materials:

Site ID: 477057
Operable Unit ID: 1226870
Operable Unit: 01
Material ID: 2224235
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Recovered:
Oxygenate:

Not reported
Not reported